CLIQ® FAQs

How will incorrect displays be corrected in the locking plan?

It can happen, e.g. after an extension import, that the display in the locking chart is no longer shown correctly.

This can be: Display of padlocks although there is no programming job, swapped fields in the E/M display, suddenly there are non-programmable fields.

To remedy this, there are key combinations that must be used in different menu items in the CLIQ Local Manager. After each successful key combination, a message box appears which must be confirmed. Please perform all three key combinations!

In the locking chart: Alt+Shift+a

In the cylinder list: Alt+Shift+e and then Alt+Shift+p

IKON
ASSA ABLOY